


CLARK-HURTH>

COMPONENTS











24000 CONVERTER HOUSING GROUP






24000
TRANSMISSION CASE & REAR COVER GROUP






18000 TURBINE SHAFT, STATOR SUPPORT, & OIL BAFFLE GROUP - WITH AUXILIARY PUMP DRIVE




CLARK-HURTH)






24000 TORQUE CONVERTER ASSEMBLY GROUP






18000 AUXILIARY PUMP DRIVE GROUP






18000 CHARGING PUMP DRIVE GROUP






24000 FORWARD SHAFT GROUP






18000 REVERSE IDLER GROUP






24000
REVERSE & 2ND SHAFT GROUP - 3 SPEED






24000 LOW SHAFT GROUP






24000 3RD SHAFT CLUTCH GROUP






24000 IDLER SHAFT GROUP




CLARK-HURTH>






18000 CHARGING PUMP & FILTER ASSEMBLY GROUP






18000 - 6 SPEED ELECTRIC CONTROL VALVE MOUNTING GROUP





18000 ELECTRIC CONTROL VALVE ASSEMBLY



HYDRAULIC DECLUTCH



Part Stocking Recommendation

The table below is a minimum spare parts inventory recommendation designated by letter code in each Service Parts List. Each letter code indicates a percentage for determining stock quantities to support the field population. Any quantity less than 1 or partial quantities need not be stocked.

Letter Code	Percentage	Example
А	15%	Part quantity = 10 per unit
		Field Population = 240 units
		Recommended stock = 240 units x 10 per unit x .15 = 360 parts
В	10%	Part quantity = 4 per unit
		Field Population = 66 units
		Recommended stock = 66 units x 4 per unit x .10 = 26.4 or 26 parts
С	6%	Part quantity = 2 per unit
		Field Population = 203 units
		Recommended stock = 203 units x 2 per unit x .06 = 24.4 or 24 parts
D	4%	Part quantity = AR*
		Field Population = 42 units
		Recommended stock = 42 units x 3 per unit x.04 = 5.04 or 5 parts
Е	2%	Part quantity = 1 per unit
		Field Population = 75 units
		Recommended stock = 75 units x 1 per unit x .02 = 1.5 or 1 part
*Part quantities denoted by "AR" (as required) should be ordered by a quantity of 3 per unit.		

© Copyright 2013 Dana Holding Corporation
All content is subject to copyright by Dana and may not
be reproduced in whole or in part by any means,
electronic or otherwise, without prior written approval.
THIS INFORMATION IS NOT INTENDED FOR SALE OR
RESALE, AND THIS NOTICE MUST REMAIN ON ALL
COPIES.

For product inquiries or support, visit www.dana.com or call 419-887-6445 For other service publications, visit www.SpicerParts.com/literature.asp For online service parts ordering, visit www.SpicerParts.com/order.asp

